
# INSTALLATION INSTRUCTIONS

## FOUR WAY DISPLAY PANEL W/PINS

### NOTE - LOAD CAPACITY:

This Display Unit has a maximum load capacity of 300 pounds on each individual panel. The total maximum load capacity for the assembled 4—panel unit is 1000 pounds.

- STEP 1: Position display base at desired location.
- STEP 2: Screw (8) 3/8"-16 x 2" LG full threaded studs into weldnuts on bottom of panel until stop on bolt meets panel (see Detail A). NOTE: The slotted end of the stud can be used with a screw driver for ease in installation.
- STEP 3: OPTIONAL BASE ATTACHMENT: If it is desired to attach the panels to the base, leave approximately 1 1/4" of exposed threads on the outside studs and install a flat washer and hex nut to the bottom side of the deck after the panels are installed (see Detail C).





# INSTALLATION INSTRUCTIONS

## FOUR WAY DISPLAY PANEL W/PINS

- STEP 4: Position display panel on base as shown. Studs will fit into holes on top of the base. NOTE: The top holes of panel should be towards the center of the base (see Detail B).
- STEP 5: Secure the top cap with  $#10 \times 5/8$ " S.M.S.

